


QUICK INSTALLATION GUIDE

TEMP/HUMIDITY/VOC DEVICE (LAN-WMBUS-E2-VOC)



Recommended mounting instructions:


- Always mount on an interior wall, e.g., hallway
- The sensor works best 180 cm above floor
- Mount the device so the holes at the front is on the right side
- Make sure that the UP symbol on the label (located on the side) is pointing upwards
- Avoid heating/cooling sources (solar radiation, lamps, pipes, extensive airflow, etc.)
- Mount the device with screws



Step 1:

Turn the device upside down.

Remove the mounting piece by pushing the two plastic pieces, marked by red circles, inwards and then lifting the piece up.




Step 2:

To activate the device, hold a permanent magnet against the label on device until a red LED turns on (the led is not bright).

Keep holding the magnet by the label until the LED turns off (after about 5 seconds).

When the LED turns off, immediately remove the magnet.

Upon successful activation the LED will continuous flash for about 10 seconds.



Step 3a:

Fasten the mounting piece to a wall with the text UP pointing upwards using the recommended mounting instructions.

Use two screws in the two holes filled with red in the picture.

Step 3b:

Mount the device on the mounting piece. Make sure the UP symbol on the label at the side of the device is pointing upwards.

Note: The ventilation slits must be on the right side.

The installation is now complete!

Step 4 (optional):

To check if the device was activated correctly, hold a magnet against the label on the device. The red LED will starts flashing immediately if it is active and it will stop flashing once the magnet is removed. If the red LED isn't flashing, redo step 2.